

Oil Field Environmental Incident Summary

Incident: 20140126185910 **Date/Time of Notice:** 01/26/2014 18:54

Responsible Party: Rud Transportation

Well Operator: OXY USA INC.

Well Name: FEDERAL TORMASCHY 2-5-8H-142-96

Field Name: MANNING

Well File #: 23057

Date Incident: 1/26/2014 **Time Incident:** 1500

Facility ID Number:

County: DUNN

Twp: 143

Rng: 96

Sec: 32

Qtr:

Location Description:

Submitted By: Dustin Tescher

Received By:

Contact Person: Dustin Tescher
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1.25 Miles

Distance Nearest Water Well: 1.25 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	1.2	barrels	1.2	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

The driver stopped filling the tank which stopped the release. A vac truck was then used to recover all of the spilled material.

Wastes Disposal Location: The recovered fluid was put into another tank to be used as frac fluid.

Agencies Involved:**Updates**

Date: 1/27/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location, according to the report. NDIC retains oversight.